



Fireeye Inc.
 3 Manchester Road
 Derry, NH 03038
 Tel 1603.432.4100 Fax 603.4321570
 www.fireeye.com

28th April 2020

REMINDER – Staged obsolescence of the Insight 1 various models & variants

This is a letter of reminder for the above (originally advised on 10th February this year). The Insight 1 Intel microprocessor and the PLD device used in many of the products have been obsolete for many years. Fireeye has covered the availability by last time, large volume purchases for a number of years.

Current availability of the Insight IV and Insight II, with plug and play replacement variants for the Insight 1 scanners, provides a modern, high capability, competitive, drop in replacement. These new products, coupled with the desire to extend the life of the remaining DS Insight variants listed in the lower table under, has supported our decision.

- Listings below for “obsolescence in May 2020” will obsolete from May 30th 2020.
- Listing below for “obsolescence in December 2020” will obsolete from December 30th 2020.
- Items listed as “parts continuing in 2021 & beyond” are forecasted to be supported for at least the next three years based on current demand levels.

Obsolescence in May 2020	
Original Part Designation	Recommended Replacement Part
95UVS1-1 (all versions including E's)	95UVS4-1WINC *
95UVS1-1CG (all versions including E's)	95UVS4-1WINC with associated cable *
95IRS1-1 (all versions including E's)	95IRS4-1WINC *
95IRS1-1CG (all versions including E's)	95IRS4-1WINC with associated cable *
95UVS2-1 (all versions including E's)	95UVS4-1WINC *
95UVS2-1CG (all versions including E's)	95UVS4-1WINC with associated cable *
95IRS2-1 (all versions including E's)	95IRS4-1WINC *
95IRS2-1CG (all versions including E's)	95IRS4-1WINC with associated cable *
95UVS2-1CEX (all versions including E's)	95UVS4-1CEX
95IRS1-1CEX (all versions including E's)	95IRS4-1CEX
60-2721-2, 60-2721-4, 60-2721-7, 60-2721-8 and	60-2984-1, 60-2984-3 **
60-2721-9, 60-2721-1, 60-2721-3	60-2984-1, 60-2984-3 **
* Use 129-193 adaptor if using with existing Fiber Optics. ** Select UV or IR as appropriate	



Fireeye Inc.
3 Manchester Road
Derry, NH 03038
Tel 1603.432.4100 Fax 603.4321570
www.fireeye.com

Obsolescence in December 2020	
Original Part Designation	Recommended Replacement Part
95DSS1-1 (all versions)	95DSS3-1WINC with display, 95DSS2-1
95DSS1-1CG (all versions)	95DSS3-1 with display and associated cables
95DSS1-1CEX (all versions including E's)	95DSS3-1CEX display included, 95DSS2-1CEX
60-2721-5	60-2721-6

Parts continuing into 2021 and beyond	
Following Insight 1 parts will continue be supported while parts are available	
95DSS2-1 (all versions including E's)	
95DSS2-1CG (all versions including E's)	
95DSS2-1CEX (all versions including E's)	
60-2721-6, 60-2721-10	

This action has been taken in an attempt to maximize the life of the Insight Dual Cell models continuing and listed directly above and preserve our ability to support the product in the field going forward.

Fireeye will of course support existing orders and/ or new orders placed and booked prior to the obsolescence dates above. As always, we intend to be as flexible as we can in supporting your projects and please contact your sales team should there be any issues or needs we can help with.

On behalf of Fireeye Inc.

Sincerely,

John Devine
General Manager
Fireeye Inc.